


BEFORE



AFTER

VACUUM CHAMBER PM TECHNIQUE VARIAN VIISTa HC PROCESS CHAMBER

OBJECTIVE:

TO EFFECTIVELY PM THE VARIAN HC PROCESS CHAMBER IN A TIMELY MANNER TO HELP MINIMIZE PARTICLE ISSUES AND IMPROVE TOOL PERFORMANCE

Vacuum Chamber:

Varian VIISTa HC

Vacuum Chamber Process Residue:

Process Induced Residue

Vacuum Chamber Components:

Process Chamber

Old Procedure:

2+ Hours using DI water & IPA with 150+ wipes

Recovery Time: 12 hours

Interval: PM process chamber every 12 weeks

New Procedure:

1.5 hour using Diamond ScrubPAD, ScrubWRIGHT™ Pen, MiraWIPE® and MiraSWABS®

Recovery time: 8 hours

PARTICLE PERFORMANCE: CHAMBER RECOVERED WITH <3 ADDERS at .16M

Vacuum Chamber Products:

VARIAN VIISTa Process Chamber PM Kit

PM Kit P/N: **HT4500-VARPC1**

- (1) [HT9423](#) CushionPAD 24" X 24"
- (1) [HT4528DC3-1](#) 280 Grit Diamond ScrubDISK®
- (1) [HT4528D-10-1](#) 280 Grit Diamond ScrubPAD
- (1) [HT4580D-10-1](#) 800 Grit Diamond ScrubPAD
- (1) [HT4513PD-10-1](#) 1350 Grit Diamond ScrubPAD
- (1) [HT4536DW-1](#) 360 Grit Diamond ScrubBELT®
- (1) [FT901](#) Soft ErgoSCRUB® Handle
- (1) [FTPEN-1](#) ScrubWRIGHT™ PEN
- (1) [HT4754](#) UltraSOLV® Sponge
- (2) [HT1511FC-5](#) MiraSWABS® (10 MiraSWABS®)
- (1) [HT5790S-25](#) MiraWIPES® (25 MiraWIPES®)
- (1) [HT4790-5](#) UltraSOLV® Wipers (5 Wipers)



VARIAN VIISta HC PROCESS CHAMBER PM PROCEDURE:

View "How to" instructional videos on <http://www.foamtecintlwcc.com/flash/>

Process Chamber Door Assembly Procedure (20 Minutes):



**VARIAN VIISta HC
PROCESS CHAMBER
DOOR BEFORE**



**VARIAN VIISta HC
PROCESS CHAMBER
DOOR AFTER**

Step 1: Using proper procedures and **safety guidelines** prepare Varian VIISta HC Process Chamber for wet clean

Step 2: Take the [HT9423](#) CushionPAD and place onto a stable working area such as a workbench or clean area on the floor (See Fig 1)

Fig 1: [HT9423](#)
CushionPAD onto
stable working area



Step 3: Place the chamber door onto the CushionPAD and remove the o-ring in preparation for wet clean

VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

Step 4: Stage the appropriate parts for wet clean (See Fig 2)

- Container of DI water
- 280D Grit ScrubDISK®
- 280D Grit ScrubPAD
- 800D Grit ScrubPAD
- 360D Grit ScrubBELT® (Not Shown)
- Soft ErgoSCRUB®
- ScrubWRIGHT™ PEN (Not Shown)
- UltraSOLV® Sponge
- MiraSWABS® (Not Shown)
- MiraWIPES®



Fig 2

Step 5: Lightly moisten the [HT4754](#) UltraSOLV® Sponge in the container of DI water and perform an initial wipe of the entire chamber door, in order to remove any loose process buildup and flakes (See Fig 3 & 4)



Fig 3: Lightly moisten UltraSOLV® with DI water

Fig 4: Wipe chamber door with UltraSOLV® Sponge to remove any flakes



Step 6: Attach the [HT4528DC3](#) 280 Grit Diamond ScrubDISK® to the [FT901](#) ErgoSCRUB® and moisten with DI water (See Fig 5 & 6)




Fig 5: 280 Grit Diamond ScrubDISK® attached to ErgoSCRUB® handle

Fig 6: Moisten ScrubDISK® with DI water



VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

Step 7: Using the 280 Grit Diamond ScrubDISK[®] attached to the ErgoSCRUB[®], scrub the deposition off a small 6" X 6" area on the chamber door (See Fig 7)

Fig 7: Use ErgoSCRUB[®] with ScrubDISK[®] and scrub a small area on chamber door



Step 8: Use the lightly dampened UltraSOLV[®] Sponge to remove the excess deposition from the chamber door (See Fig 8 & 9)



Fig 8 & 9: Lightly dampened UltraSOLV[®] Sponge wiping away excess deposition



Step 9: Unload the deposition from the Diamond ScrubDISK[®] by pulling and twisting across the UltraSOLV[®] Sponge (See Fig 10, 11 & 12)




Fig 10: ScrubDISK[®] loaded with deposition



Fig 11: Pull & twist ScrubDISK[®] across UltraSOLV[®] Sponge




Fig 12: Unloaded ScrubDISK[®]

VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

Step 10: Using the same technique described above, continue to lightly moisten the ScrubDISK[®] and scrub off the deposition, then use the UltraSOLV[®] Sponge to remove the excess deposition from the remaining area on the chamber door (See Fig 13 & 14)



Fig 13:
Scrubbing deposition from remaining areas on chamber door



Fig 14: Wiping away excess deposition with UltraSOLV[®] Sponge

Step 11: After using the Diamond ScrubDISK[®] take the [HT4528D](#) 280 Grit Diamond ScrubPAD and using the same technique described above, remove any remaining deposition left on chamber door (See Fig 15)

Fig 15: Diamond ScrubPAD removing remaining deposition on chamber door



VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

Step 12: Continue to use the UltraSOLV® Sponge to remove excess deposition from chamber door; remember to rinse out UltraSOLV® Sponge and keep lightly dampened with DI water (See Fig 16 & 17)



Fig 16: UltraSOLV® Sponge loaded with deposition



Fig 17: UltraSOLV® Sponge free of deposition after rinse in DI water

Step 13: Turn the chamber door onto its side and using the [HT4528D](#) 280 Grit Diamond ScrubPAD and UltraSOLV® Sponge remove the deposition from the lip of the viewing window (See Fig 18 & 19)



Fig 18: Diamond ScrubPAD scrubbing deposition from lip of chamber door



Fig 19: UltraSOLV® Sponge removing excess deposition from lip of chamber door

VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

Step 14: Place the [HT4536DW](#) 360 Grit Diamond ScrubBELT® onto the [FTPEN-1](#) ScrubWRIGHT™ Pen and use it to reach the tight corners around the viewing window (See Fig 20 & 21)



Fig 20 & 21: ScrubWRIGHT™ Pen used for more detailed work around viewing window



Step 15: When deposition has been completely removed from chamber door, take the [HT4580D](#) 800 Grit Diamond ScrubPAD and using the same technique described above, gently polish over all the areas where the 280 Grit ScrubPAD was used – this will help keep the chamber in a polished state (See Fig 22)



Fig 22: 800 Grit Diamond ScrubPAD used to polish chamber door after initial scrub

Step 16: Take the [HT4513PD](#) 1350 Grit Diamond ScrubPAD and, with plenty of DI water, **GENTLY** scrub off the deposition from the chamber viewing window (See Fig 23)

Fig 23: 1350 Grit Diamond ScrubPAD gently removing deposition from window



VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

NOTE: IT IS IMPORTANT TO USE PLENTY OF DI WATER WHEN USING THE 1350 GRIT ScrubPAD ON THE VIEWING WINDOW TO PREVENT SCRATCHING WINDOW

Step 17: Continue to use UltraSOLV[®] Sponge as before to remove the excess deposition from viewing window (See Fig 24)



Fig 24: UltraSOLV[®] Sponge removing excess deposition from viewing window

Step 18: Rinse out the UltraSOLV[®] Sponge with DI water and wipe the entire chamber door assembly in preparation for the Final Wipe Procedure

VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

FINAL WIPE PROCEDURE OF CHAMBER DOOR:

VERY IMPORTANT NOTE

THE USE OF HT5790S MiraWIPES® AND HT1511FC MiraSWABS® DURING THE FINAL WIPE PROCEDURE IS A CRITICAL STEP TO EFFECTIVELY REMOVE PARTICLE DEFECTS FROM PROCESS CHAMBER DOOR

NOTE: BELOW IS AN EXAMPLE OF THE PARTICLES LEFT BEHIND IN A PROCESS CHAMBER AFTER THE FINAL WIPE PORTION OF THE PM WAS PERFORMED USING THE CURRENT FAB WIPER (SEE FIG 25a & 25b)

Fig 25a: Current fab wiper after completely wiping chamber



Fig 25b: Particles picked up using HT5790S MiraWIPES® after completely wiping with current fab wiper

MiraWIPES® are the KEY STEP for DEFECT REDUCTION and IMPROVED TOOL RECOVERY

Step 19: Saturate the HT5790S MiraWIPE® with IPA and perform an initial wipe of the chamber door (See Fig 26 & 27)



Fig 26: Saturating HT5790S MiraWIPES® with IPA

Fig 27: Performing an initial wipe of chamber door



VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

Step 20: Take the [HT1511FC](#) MiraSWAB[®] and place on a [HT5790S](#) MiraWIPE[®], and then saturate the MiraSWAB[®] with IPA (See Fig 28)

Fig 28: Saturating [HT1511FC](#) MiraSWABS[®] with IPA



Step 21: Take the saturated MiraSWAB[®] and wipe deposition out of all the tight corners and hard to reach areas, such as o-ring grooves (See Fig 29, 30 & 31)



Fig 29 & 30: MiraSWABS[®] cleaning out tight areas and grooves along Process Chamber Door



Fig 31: EXTRA DEPOSITION THE MiraSWABS[®] ARE ABLE TO REMOVE FROM AREAS ON CHAMBER DOOR

VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

MiraWIPES[®] and MiraSWABS[®] are the KEY STEPS for DEFECT REDUCTION and IMPROVED TOOL RECOVERY

Step 22: Continue to saturate the [HT5790S](#) MiraWIPE[®] with IPA and perform a final wipe of the chamber door until no further deposition is removed from door assembly (See Fig 32)



Fig 32: Completed Process Chamber Door PM

VIISta HC Process Chamber PM (1 Hour):

Step 23: Using proper procedures and **safety guidelines** prepare Varian VIISta HC Process Chamber for wet clean

Step 24: In preparation for Process Chamber wet clean, carefully cover the electrostatic clamp with a large plastic bag and place a light within the chamber (See Fig 33 & 34)




Fig 33 & 34: Electrostatic clamp carefully covered with large plastic bag



VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

Step 25: Stage the appropriate parts needed for Process Chamber PM, most of the parts will be the same parts used for the Chamber Door PM

- Container of DI Water
- 280D Grit ScrubDISK[®]
- 280D Grit ScrubPAD
- 800D Grit ScrubPAD
- Soft ErgoSCRUB[®]
- UltraSOLV[®] Sponge
- MiraSWABS[®] (Not Shown)
- MiraWIPES[®]

NOTE: THE PROCESS CHAMBER PM WILL FOLLOW THE SAME TECHNIQUE DESCRIBED ABOVE FOR THE PROCESS CHAMBER DOOR PM

Step 26: Lightly moisten the UltraSOLV[®] Sponge in the container of DI water and perform an initial wipe of the area that will be cleaned inside the Process Chamber, in order to remove any loose process buildup and flakes

Step 27: Attach the [HT4528DC3](#) 280 Grit Diamond ScrubDISK[®] to the [FT901](#) ErgoSCRUB[®] and moisten with DI water (See Fig 35)




Fig 35: 280 Grit Diamond ScrubDISK[®] attached to ErgoSCRUB[®]

VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

Step 28: Using the 280 Grit Diamond ScrubDISK[®] attached to the ErgoSCRUB[®], scrub the deposition off a small 6" X 6" area within the process chamber (See Fig 36)

Fig 36: 280 Grit Diamond ScrubDISK[®] scrubbing deposition from Process Chamber



Step 29: Use the lightly dampened UltraSOLV[®] Sponge and proceed to remove the excess deposition from the scrubbed area within the process chamber

Step 30: Unload the deposition from the Diamond ScrubDISK[®] by pulling and twisting across the UltraSOLV[®] Sponge (See step 9 of Chamber Door Procedure)

Step 31: Using the same technique described above, continue to lightly moisten the ScrubDISK[®], scrub off the deposition, and use the UltraSOLV[®] Sponge to wipe the excess deposition from the remaining areas in the process chamber

Step 32: After using the Diamond ScrubDISK[®] take the [HT4528D](#) 280 Grit Diamond ScrubPAD and using the same technique described above, remove any remaining deposition left in the area to be scrubbed in the process chamber (See Fig 37)

Fig 37: ScrubPAD cleaning all remaining areas within process chamber



VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

Step 33: When deposition has been completely removed from the area to be cleaned in the chamber, take the [HT4580D](#) 800 Grit Diamond ScrubPAD and, using the same technique described above, gently polish over all the areas where the 280 Grit Diamond ScrubPAD was used – this will help keep the process chamber in a polished state (See Fig 38)



Fig 38: 800 Grit Diamond ScrubPAD polishing process chamber

FINAL WIPE PROCEDURE OF PROCESS CHAMBER:

VERY IMPORTANT NOTE

THE USE OF [HT5790S](#) MiraWIPES® AND [HT1511FC](#) MiraSWABS® DURING THE FINAL WIPE PROCEDURE IS A CRITICAL STEP TO EFFECTIVELY REMOVE PARTICLE DEFECTS FROM PROCESS CHAMBER

NOTE: BELOW IS AN EXAMPLE OF THE PARTICLES LEFT BEHIND IN A PROCESS CHAMBER AFTER THE FINAL WIPE PORTION OF THE PM WAS PERFORMED USING THE CURRENT FAB WIPER (SEE FIG 39A & 39b)

Fig 39a: Current fab wiper after completely wiping chamber



Fig 39b: Particles picked up using [HT5790S](#) MiraWIPES® after completely wiping with current fab wiper

MiraWIPES® are the KEY STEP for DEFECT REDUCTION and IMPROVED TOOL RECOVERY.

VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

Step 34: Carefully remove the plastic bag over the electrostatic clamp

Step 35: Saturate the [HT5790S](#) MiraWIPE® with IPA and perform a final wipe of the process chamber (See Fig 40)



Fig 40: Using the [HT5790S](#) MiraWIPES® to complete a final wipe of the process chamber

Step 36: Take the [HT1511FC](#) MiraSWAB® and place into a MiraWIPE®, and then proceed to saturate the MiraSWAB® with IPA (See Fig 41)

Fig 41: Using the [HT1511FC](#) MiraSWABS® to wipe out the tight corners and hard to reach areas



Step 37: Continue to saturate the remaining MiraWIPES® with IPA and wipe out the process chamber until no further visible deposition is being removed by the MiraWIPE®

Step 38: In order to help minimize back side particle problems it is important to use the [HT4790](#) UltraSOLV® Foam Wiper to wipe the face of the electrostatic clamp – this will be the last step just prior to closing up the Process Chamber

VARIAN VII STA HC PROCESS CHAMBER PM PROCEDURE (CONT'D):

Step 39: Take a **dry** [HT4790](#) UltraSOLV[®] Foam Wiper and fold into quarters, then wipe the face of the electrostatic clamp by pulling the foam wiper from the back to the front of the face (See Fig 42)

Fig 42: Using the [HT4790](#) UltraSOLV[®] Foam Wiper to wipe the face of the ESC from BACK to FRONT



Step 40: Refold the UltraSOLV[®] Foam Wiper exposing a clean side of the wiper and continue to wipe the remaining areas of the electrostatic clamp

Step 41: Using the approved **safety procedures and guidelines** close the process chamber and return the tool back to production